

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

002750" 64009960




Fig. 1





Fig. 2A

Fig. 3



002160" 64009960

002760" 64009960




Fig. 4

Fig. 5





Fig. 6



002160" 54009960




Fig. 7




Fig. 8

Fig. 9




Fig. 10




Fig. 11





Fig. 12

002760 6409960




Fig. 14





Fig. 13

002150" 64009960

Fig. 15



9/21

9/28

10









Fig. 16

002160" 64009960

Fig. 17



Reduce
1



002160" 64009960




Fig. 22




Fig. 24




Fig. 23




Fig. 25

002160" 64009960

FIG. 26





Fig. 28




Fig. 27

09650049-091200

Fig. 29





Fig. 30




Fig. 31




Fig. 40




Fig. 41

002160" 6409960

002F60" 6409960




Fig. 32




Fig. 33



Fig. 34




Fig. 35




Fig. 37




Fig. 36




Fig. 38




Fig. 39

002160" 64009960

DATE 7/2/0

18/28

18/28




Fig. 4.3

Reduce

19/28




Fig. 42




Fig. 44




Fig. 45

002260" 6409960

002160" 64009960




Fig. 46




Fig. 47




Fig. 48




Fig. 49






Fig. 50

002160" 64009960






Fig. 53




Fig. 54

002160" 6409960

23/28




Fig. 55

002160" 64009960

002160" 64009960




Fig. 56

99
~~XX~~




Fig. ~~56~~ 57




Fig. ~~57~~ 58




Fig. ~~58~~ 59




Fig. ~~59~~ 60




Fig. ~~60~~ 61




Fig. 62






Fig. 63

09660049, 091200



09650049-091200




Fig. 45 66




Fig. 46 67




Fig. 47 68

002160" 64009960